

1  
2  
3  
4  
5  
6  
7  
8  
9  
10  
11  
12  
13  
14  
15  
16  
17  
18  
19  
20  
21  
22  
23  
24  
25  
26  
27  
28  
29  
30  
31  
32  
33  
34  
35  
36  
37  
38  
39  
40

## DRAFT FINAL REPORT

# Crash of Malaysia Airlines Boeing 777-200, 9M-MRD, flight MH17

Hrabove, Ukraine, 17 July 2014

DRAFT - NOT FOR PUBLICATION

RELEASE

*The Hague, 2 June May 2015*

*The reports issued by the Dutch Safety Board are open to the public.*

*All reports are also available on the Safety Board's website [www.safetyboard.nl](http://www.safetyboard.nl)*



1	<b>Contents</b>	
2		<b>Summary..... 7</b>
3		<b>Abbreviations &amp; Definitions ..... 9</b>
4	<b>1</b>	<b>Introduction ..... 16</b>
5	1.1	The investigation ..... 16
6	1.2	Other, related, investigations..... 17
7	1.3	Purpose and scope of the investigation..... 18
8	1.4	Investigation approach and parties concerned ..... 18
9	1.5	Preliminary Report published on 9 September 2014 ..... 20
10	1.6	Wreckage recovery ..... 22
11	1.7	Reading guide ..... 23
12	<b>2</b>	<b>Factual information..... 25</b>
13	2.1	History of the flight..... 25
14	2.2	Injuries to persons ..... 29
15	2.3	Damage to the aircraft..... 29
16	2.4	Other damage ..... 30
17	2.5	Personnel information ..... 30
18	2.6	Aircraft information ..... 32
19	2.7	Meteorological information ..... 34
20	2.8	Aids to navigation ..... 38
21	2.9	Air Navigation Service Provider information ..... 39
22	2.10	Aerodrome information ..... 49
23	2.11	Flight recorders, satellite and other data ..... 50
24	2.12	Wreckage and impact information ..... 60
25	2.13	Medical and pathological information ..... 73
26	2.14	Fire ..... 74
27	2.15	Survival Aspects..... 75
28	2.16	Tests and research..... 75
29	2.17	Organisational and management information..... 78
30	2.18	Additional information ..... 78
31	2.19	Useful or effective investigation techniques ..... 84
32	<b>3</b>	<b>Analysis ..... 89</b>
33	3.1	Introduction..... 89
34	3.2	Before the moment of high-energy object impact..... 89
35	3.3	The moment of high-energy object penetration ..... 95
36	3.4	Sources of in-flight aeroplane structural failure ..... 104
37	3.5	Multiple weapon impacts ..... 116

This is a copy of the draft Final Report of this investigation intended solely for consultation as per ICAO Annex 13, paragraph 6.3. It shall not be released to or communicated with parties other than those to whom the report is addressed.

1	3.6	External damage exacerbated by airworthiness factors .....	117
2	3.7	Source of the high-energy objects.....	118
3	3.8	Launch area .....	131
4	3.9	Second progress meeting.....	133
5	3.10	Blast damage .....	133
6	3.11	After the high-energy object penetration .....	136
7	3.12	Summary and possible impact on flight crew .....	156
8	3.13	Recording of surveillance radar data.....	156
9	<b>4</b>	<b>Conclusions .....</b>	<b>159</b>
10	4.1	Cause.....	159
11	4.2	Supporting conclusions .....	159
12	4.3	Excluding other causes .....	162
13	4.4	Other findings .....	164
14	<b>5</b>	<b>Recommendations.....</b>	<b>165</b>
15			

DRAFT - NOT FOR PUBLIC RELEASE

1	<b>Appendices</b>	
2	<b>Appendix A: Explanation of the Investigation .....</b>	<b>167</b>
3	<b>Appendix B: Responses received following review of the draft report .....</b>	<b>179</b>
4	<b>Appendix C: Memorandum of Understanding .....</b>	<b>181</b>
5	<b>Appendix D: Agreement between NBAAI and DSB .....</b>	<b>183</b>
6	<b>Appendix E: Reference information .....</b>	<b>187</b>
7	<b>Appendix F: Air Traffic Control flight plan .....</b>	<b>191</b>
8	<b>Appendix G: NOTAM information .....</b>	<b>193</b>
9	<b>Appendix H: Load information .....</b>	<b>203</b>
10	<b>Appendix I: Weather charts and images .....</b>	<b>205</b>
11	<b>Appendix J: Transcripts .....</b>	<b>207</b>
12	<b>Appendix K: Recorder group work .....</b>	<b>219</b>
13	<b>Appendix L: Radar screen images.....</b>	<b>227</b>
14	<b>Appendix M: Aeroplane systems and engines information.....</b>	<b>233</b>
15	<b>Appendix N: Typical fracture modes .....</b>	<b>247</b>
16	<b>Appendix O: Wreckage location and distribution .....</b>	<b>251</b>
17	<b>Appendix P: NLR report into the source of high-energy objects.....</b>	<b>275</b>
18	<b>Appendix Q: Presentation by Almaz-Antey.....</b>	<b>337</b>
19	<b>Appendix R: TNO report on the Numerical simulation of blast loading .....</b>	<b>353</b>
20		
21		

1 **2.11 Flight recorders, satellite and other data**

2 2.11.1 Recovery of Cockpit Voice Recorder and Flight Data Recorder

3 The Cockpit Voice Recorder and Flight Data Recorder were not recovered from the  
4 wreckage site by investigators of the Annex 13 investigation team, but individuals  
5 unknown to the team removed the two recorders from the accident site. On 21 July  
6 2014, the recorders were handed over to a Malaysian official in Donetsk by  
7 representatives of the armed group controlling the area. No evidence or indications  
8 of manipulation of the recorders were found. On 22 July 2014, the recorders were  
9 handed over to the Dutch Safety Board in Kiev. Appendix K contains further  
10 information on the Cockpit Voice Recorder and Flight Data Recorder.

11  
12 It should be noted that the images for both recorders show two sets of texts, one in  
13 Cyrillic text and one in French. The label in French, repeated in English on the other  
14 side of the unit, is placed there by the manufacturer, Honeywell. The Cyrillic text on  
15 the sticker on the unit states “*The Prosecutor General’s Office of the Donetsk*  
16 *People’s Republic*” This was not added by the Dutch Safety Board but was on both  
17 data recorders when they were handed over to the Safety Board.

18 2.11.2 Cockpit Voice Recorder

19 The housing of the Cockpit Voice Recorder (Figure 8) was damaged and, although  
20 the model and serial numbers are unreadable on the datum plate, the serial number  
21 1366, matching the one provided by Malaysia Airlines, is stamped on the underside  
22 of the chassis. The external damage on the Cockpit Voice Recorder is consistent  
23 with impact damage; the internal memory module was intact. The Cockpit Voice  
24 Recorder was successfully downloaded and contained valid data from the flight.

25



26

27 *Figure 8 – Cockpit Voice Recorder (Source: DSB)*


28

1 The replay of the Cockpit Voice Recorder matched Air Traffic Control  
 2 communications with flight MH17 (see Air Traffic Control transcript). The recording  
 3 also included crew communication which gave no indication that there was anything  
 4 abnormal with the flight. The Cockpit Voice Recorder audio recording ended  
 5 abruptly at 13.20:03 (15.20:03 CET). A replay of the Cockpit Voice Recorder did not  
 6 identify any aeroplane aural warnings or alerts of system malfunctions. It was noted  
 7 that on one of the four channels of audio, the cockpit area microphone, the sound  
 8 quality was poor. The relevant parts of the Cockpit Voice Recorder recording are  
 9 integrated with the Air Traffic Control transcript in Appendix K of this report.

10

11 Crew communication gave no indication that there was anything abnormal with the  
 12 flight. At the very end of the recording, two peaks of sound were identified on the  
 13 last 20 milliseconds of the recording. A graphic representation of the two peaks of  
 14 sound for the four Cockpit Voice Recorder microphones are shown here.

15



16 *Figure 9 – Sound peaks recorded at the end of the CVR recording (Source: DSB)*

17

18 The time period shown on each image is four hundredths of a second. It is noted  
 19 that peak of sound 'peak 1' is only recorded on the CAM.

### 20 2.11.3 Flight Data Recorder

21 The housing of the Flight Data Recorder (Figure 10) Allied Signal Model Number  
 22 980-4700-003, has Serial Number 2196. The details match the details provided by  
 23 Malaysia Airlines. The recorder that was given to the Dutch Safety Board had no  
 24 Underwater Locator Beacon attached. As this beacon is activated by submersion in  
 25 water, its activation is not expected.

26

27 The recorder is damaged but the internal memory module is intact. The external  
 28 damage on the Flight Data Recorder is consistent with impact damage. The Flight  
 29 Data Recorder, which can record 25 hours of operational data, was successfully  
 30 downloaded and contained valid data from the occurrence flight.

31

## 1 **2.12 Wreckage and impact information**

2

3 The following paragraphs describe the geographic area of the accident and  
4 wreckage as it was found. Details are provided on the location, identification and  
5 observed damage of the wreckage pieces.

### 6 **2.12.1 Accident site access**

7 Due to the security situation within the geographic area of the crash, the Dutch  
8 Safety Board was unable to start the collection and preservation of the wreckage  
9 directly after the crash.

10

11 Under escort of the OCSE, air accident investigators from Australia, Ukraine and  
12 Malaysia, the Australian Federal Police and journalists had access to the crash area  
13 in the days following the accident. During these visits, the wreckage was  
14 photographed extensively and showed the locations mostly undisturbed.

15

16 It was not until 4 November 2014 that the Dutch Safety Board was able to visit the  
17 various locations where the wreckage was located, under the protection of the  
18 Dutch Ministry of Defence's Recovery Mission. On 15 November, after receiving  
19 permission from local authorities, wreckage parts were collected during 6 days and  
20 transported to the Netherlands for the investigation and partial reconstruction of the  
21 fuselage. It was necessary to cut some parts into smaller pieces for transport.

22

23 It was not until 20 March 2015 that it was possible to gain access to the area  
24 northwest of the village of Petropavlivka for the first time. From 19 April until 2 May  
25 more pieces of wreckage were recovered with the assistance of the local residents.

26

27 It should be noted that many parts of the wreckage were not physically examined by  
28 the Dutch Safety Board until four months after the accident. During this period parts  
29 were also removed, taken away or collected. Wherever possible, the photographs  
30 taken immediately after the accident were used in conjunction with the wreckage  
31 found.

### 32 **2.12.2 General distribution of wreckage and distribution diagrams**


33 The wreckage parts of the aeroplane were identified in six concentrated areas to the  
34 west and south-west of the village of Hrabove, within an area of approximately 50  
35 km<sup>2</sup>. Figure 12 shows the geographic location of the six wreckage areas. Each  
36 wreckage area has an associated colour, depicted in figures 13 and 14.

37





1

2 *Figure 12 – Overview wreckage areas with wreckage parts*

3

4

5 *Figure 13 – Side view left and right. Identification of wreckage retrieved from the*  
6 *wreckage areas (Source: DSB)*

7

8 The following table gives an overview of the wreckage areas that are described in  
9 this paragraph. A detailed description of the primary wreckage parts and their  
10 location is presented in Appendix O.

11

12

Wreckage site no.	Colour code	Notes	Paragraph	Appendix O
1	Orange	An open area of farming land	2.12.2.1	Fig. O.1
2	Red	Residential area of Petropavlivka	2.12.2.2	Fig. O.1
3	Light grey	An area of farming land south of the village of Rozsypne	2.12.2.3	Fig. O.1
4	Yellow	A built-up area partially surrounded by a forest in a gully	2.12.2.4	Fig. O.2
5	Green	An area of farming land separated by an elevated road	2.12.2.5	Fig. O.3
6	Blue	An area of farming land separated by an elevated road southwest of the village of Hrabove	2.12.2.6	Fig. O.4
0	Black	Parts of wreckage of which the initial location could not be verified	2.12.2.7	-

1 *Table 12 – Overview description of wreckage sites in this report*

2

3 It was noted that no parts of wreckage were identified between the areas 3 and 4.

4

5 For each wreckage area, a description of the wreckage parts relevant for the  
6 analysis is given. A more detailed description of the wreckage pieces of interest can  
7 be found in Appendix O.

8

9 In the description of the damage to the aeroplane Boeing references such as  
10 sections and stations (STA) are used. Information on these two means of reference  
11 is provided under Abbreviations & Definitions.

#### 12 2.12.2.1 – Wreckage area 1 (orange)

13 Parts of the fuselage originating from section 41, including parts of the cockpit  
14 fuselage, the fuselage above the business class, cockpit and cabin furnishing, and  
15 fragments of two cargo containers, were located in area 1. This area of  
16 approximately 3 km<sup>2</sup>, is located 8.8 km west of the village of Hrabove. Parts of  
17 wreckage were distributed over three agricultural fields which were separated by  
18 roads and vegetation. No fire nor infrastructure damage was observed in this area.  
19 Due to shelling, the Dutch Safety Board was unable to access area 1 during the  
20 recovery mission in November 2014.

1 2.12.2.2 Wreckage area 2 (red)

2 The pieces of wreckage of the forward section of the aeroplane, including the  
3 doorframe and surrounding fuselage of doors 1L, 2L, 1R and 2R and the cargo  
4 floor, originating from section 43 of the aeroplane, were located in area 2. This area  
5 of approximately 2.5 km<sup>2</sup>, covers a large part of the village of Petropavlivka and is  
6 located 8 km west of Hrabove. As a result of fallen debris, several structures within  
7 the village of Petropavlivka had sustained damage. Due to shelling access to area 2  
8 was restricted. The Dutch Safety Board was unable to retrieve all parts identified in  
9 area 2 during the recovery mission in November 2014.

10

11 *Fuselage with negative pressure relief valves*

12 The fuselage containing door 2R was identified in the south-eastern region of area  
13 2. The passenger door was positioned in its doorframe and the fuselage had  
14 sheared below the frame of the left negative pressure relieve valve. The left  
15 negative pressure relief valve was attached to the upper portion of the frame and  
16 the door was pinned in its open position between the casing and the ground.  
17 Neither the frame nor the valve of the right negative pressure relieve valve were  
18 found in area 2.

19

20 *Engine Inlet ring*

21 The leading edge of the left engine casing was found in the south-eastern region of  
22 area 2. The ring showed penetration damage on approximately the 40, 50, 60, 135,  
23 180, 200, 290 and 300 degree positions, looking forward.

24



25 *Figure 14 – Damaged left engine nacelle leading edge (left) and impact marks at*  
26 *the 200 degree position shown from the rear side (right) (Source: DSB)*

1 2.12.2.3 Wreckage area 3 (light grey)

2 The cockpit and surrounding fuselage of section 41 was found in area 3, 6.2 km  
3 south-west of Hrabove. The area, approximately 67 x 37 m, was located in a  
4 sunflower field situated on the southern corner of the village of Rozsypne. Within a  
5 relatively concentrated area, cockpit instruments, avionics equipment and fragments  
6 of cabin- and cargo furnishing were found. Aside from flattened vegetation, shallow  
7 impact marks were observed on the ground

8

9 Photographic- and video evidence from the days after the crash indicated that area  
10 3 had been disturbed and aeroplane parts and cargo had been removed from the  
11 site. A number of avionics units, photographed by third parties following the days of  
12 the accident, were no longer present during the recovery mission of the Dutch  
13 Safety Board in November 2014.

14

15 *General description cockpit and surrounding fuselage.*

16 The forward portion of the aeroplane, part of the cockpit including the forward  
17 bulkhead, was found in a tilted nose down position facing in easterly direction. The  
18 cockpit and surrounding fuselage had separated in longitudinal direction of the  
19 aeroplane revealing cockpit and cabin furnishing.

20

21 Within the relatively concentrated area, a number of wreckage pieces, varying in  
22 size, lay in a heap. The nose landing gear wheel bay and the avionics compartment  
23 had penetrated the cockpit and cabin floor pushing it in an upward direction. The  
24 adjacent cabin floor had separated in the longitudinal direction of the aeroplane  
25 after which two portions of the floor existed. The left portion of the cabin floor was  
26 still attached to the fuselage and fragments of the left galley were observed. Other  
27 than the severe structural damage of the fuselage, the bottom portion of the  
28 fuselage was found as a whole. The fuselage on the right side of the aeroplane had  
29 sheared behind the large cargo door and the adjacent cargo floor was visible.

30

31 On the left side of the cockpit, between STA132.5 and STA220.5 of the aeroplane,  
32 no pieces of fuselage were observed. The left Angle of Attack sensor, still attached  
33 to a portion of the fuselage, was located in the vicinity of the wreckage.

34

35 Aside from damage, the right side of the cockpit remained fairly intact. In contrast to  
36 the left side of the cockpit, the lower right side showed little signs of penetration  
37 from the outside as shown in Figure 15. It was noted that the upper portion of the  
38 right side of the fuselage was penetrated and the windshield of the right cockpit  
39 windows was still in place.

40

1



2

3 *Figure 15 – Upper right hand side of the cockpit as found on the crash site (Source:*  
 4 *DSB)*

5

6 Within close proximity of the wreckage, cockpit furnishing, including pilot seats and  
 7 cockpit instruments were identified. Together with the parts of the cockpit floor, the  
 8 throttle quadrant and pedestal had been pushed in an upward direction. The  
 9 remainder of the cockpit instruments such as the Mode Control panel and a number  
 10 of cockpit display units were found in a heap.

11



12

13 *Figure 16 - Cockpit floor with floor parts showing penetration holes (red circles)*  
 14 *coming from above the floor, penetrating downwards (source: NBAAI)*

15

16 A large part of the cockpit floor was recovered, Figure 16, broken up in several  
 17 parts, and stripped from most of its contents. Seats, centre console, wall structure  
 18 and most of the control mechanics were separated from the floor structure; only part

1 of the co-pilot control mechanism remained attached. Figure 17 shows an overview  
2 of the recovered floor parts.  
3



4  
5 *Figure 17 - Cockpit floor overview partially reconstructed in Gilze-Rijen (Source:*  
6 *DSB)*

7  
8 The outer left side, effectively left of the captain's seat, is covered in soot and has a  
9 large number of holes of different sizes are noted. The curved metal parts on the  
10 floor are the forward and aft tracks of the captain's seat. Smaller numbers of impact  
11 holes were present in other locations, including just left of the first observer seat and  
12 below the second observer seat.

#### 13 2.12.2.4 Wreckage area 4 (yellow)

14 The fuselage of the aeroplane between the wing- and the tail section was primarily  
15 located in Area 4, approximately 2 km south-southwest of Hrabove. Parts of  
16 wreckage, including both stabilizers and both wingtips were distributed over an area  
17 of approximately 540 x 650 m. The area contains a number of buildings surrounded  
18 by a fence. The area was partially surrounded by a forest which was located in a  
19 gully. The right stabilizer was found in a pond in the south-easterly part of the area.

#### 20 21 *Right wing tip*

22 The right wingtip was located near the buildings in the south westerly region of area  
23 4. The wing tip was facing in a south easterly direction and was lying upside down.  
24 The wing tip had sheared from the wing at the fourth fuel tank vent hatch, counting  
25 from the tip towards the root. The Safety Line Attach Points were visible on the top  
26 side of the wing tip. The aileron was missing.

27  
28  
29

1 *Left wing tip*

2 The left wing tip was located near the pond in the south easterly region of area 4,  
3 with its top side facing upwards and the tip in a north westerly region. The Safety  
4 Line Attach Points were visible on the top side of the wing tip. The tip showed signs  
5 of impact damage on the top side and the leading edge. The wing tip broke off from  
6 the wing at the fourth fuel tank vent hatch, counting from the tip towards the root.  
7



8

9 *Figure 18 – Left wing tip with impact damage (Source: ATSB)*

10 *Rear pressure bulkhead*

11 The rear pressure bulkhead was separated into four pieces. A small portion of the  
12 rear pressure bulkhead was still attached to the fuselage surrounding door 4L. The  
13 largest piece was found in the forest in the gully in the northern region of area 4.  
14 The remaining part of the rear pressure bulkhead is missing.

15 2.12.2.5 Wreckage area 5 (green)

16 The aft section of the aeroplane including the vertical tail and the surrounding  
17 fuselage was primarily located in area 5, situated approximately 730 meters south  
18 of Hrabove. Within the area, pieces of wreckage were distributed over  
19 approximately 600 x 800 metres. On the western side of the elevated road a  
20 concentrated debris area was identified. Within this area cabin items and cargo  
21 were found. These parts were consumed by fire. Parallel to the elevated road on the  
22 west side, there were power lines. It was noted that one of the power lines on the  
23 west side of the elevated road had been clipped.

1 Photographic evidence and satellite imagery showed that the wreckage site was  
2 disturbed on 17 July 2014 and pieces of wreckage were repositioned.

3

4 *Horizontal stabilizer - front spar*

5 The horizontal stabilizer front spar was detached from its housing and was situated  
6 on the elevated road besides the aft portion of the tail. Fragments of the right  
7 horizontal stabilizer were still attached to the front and rear spar of the horizontal  
8 stabilizer. The front part of the stabilizer box showed impact marks in a lateral  
9 direction. The left bushing of the horizontal stabilizer jackscrew fitting was missing.

10

11 *Vertical stabilizer*

12 The vertical stabilizer was located on the east side of the elevated road with the top  
13 part of the stabilizer facing in the south-south-westerly direction. The left side of the  
14 vertical stabilizer was facing upwards. The upper part of the leading edge including  
15 the horn balance and rudder control surface were missing. A small portion of the  
16 fuselage of the left hand side of the aeroplane was still attached to the vertical  
17 stabilizer.

18 2.12.2.6 Wreckage area 6 (blue)

19 Wreckage area 6 is situated in the south-westerly corner of the village of Hrabove  
20 and measures approximately 240 x 290 metres. Within this area, a smaller region  
21 with a higher intensity fire was observed, measuring approximately 40 x 60 metres.  
22 This smaller region contained all large pieces of wreckage except the forward keel  
23 chord. Pieces of wreckage were distributed over two sub-areas, a northern and  
24 southern area, separated by an elevated road. Photographic evidence and satellite  
25 imagery showed that the wreckage site was disturbed on 18 July 2014 and pieces  
26 of wreckage were repositioned. The centre section of the aeroplane, including parts  
27 of the wings and both engines were located in area 6.

28

29 A fire occurred on the corner of the residential area on the east side of area 6. Both  
30 sub-areas included vegetation, infrastructure and pieces of wreckage that showed  
31 signs of fire damage. A wooden fence and a haystack were damaged by fire.

32

33 Fragments of the wings were primarily located on the southern region of area 6. The  
34 remains of the wings showed extensive fire damage. The wings were found upside  
35 down with the tank hatches, including the screws holes and placards and markings,  
36 showing on the upward facing side of the wings.

37

38

39



1 The left wing was situated parallel to the elevated road in the western corner of area  
2 6. The remains of the wing contained partial markings of the aeroplane's  
3 registration; "9" and "M". The tank hatches as well as the screw holes were visible.  
4 The left wing near the partial registration was relatively intact. Further along the  
5 wing, towards the root, melted aluminium was observed. Based on the partial  
6 registration, the presence of the tank hatches and the screw holes, it was  
7 determined that the left wing was situated in the south side of area 6 with its wing tip  
8 facing in south westerly direction.

9

10 The right wing was situated perpendicular to and across the road. The wing  
11 contained placards and markings stating "Fuel Tank Vent Right Wing" indicating the  
12 right wing. The portion of the wing, below the tip, was relatively intact and no fire  
13 damage was visible. Further along the wing, towards the root, the tank hatches  
14 were no longer visible. Pieces of melted aluminium suggest that parts of the wing  
15 were consumed by fire. Based on the sequence of the tank hatches, the presence  
16 of placards and markings and the visibility of the tank hatch screws, it was  
17 determined that the right wing was situated across the elevated road with its tip  
18 facing north.

19

20 Both the left and right engines were separated from the wing and had impacted the  
21 ground in a slightly inverted attitude. Both fans were found detached and the fan  
22 blades of both engines remained in place in their discs. The engines were located in  
23 the southern region of area 6.

24

25 The left engine was located near the left wing. The main core of the left engine had  
26 split into two sections. The front part of the engine was facing north and the aft part  
27 of the engine was facing west. As the fan blades and the intermediate compressor  
28 blades of the left engine showed little evidence of any rotation at impact.

29

30 The right engine was located on the south side of area 6, parallel to the elevated  
31 road. The main core of the right engine was relatively intact with its forward side  
32 facing west. The right engine was located near the right wing and was separated  
33 from the wing. Both main landing gear legs were located on the side of the elevated  
34 road. With the landing gear bogies still attached. All the tyres on the main landing  
35 gear were consumed by fire and the wheel rims were visible.

36

37

38

1 2.12.2.7 Wreckage area 0 (black)

2 Pieces of wreckage of which the initial location of impact on the ground could not be  
3 verified due to insufficient photographic and video evidence are listed in area 0.  
4 These wreckage pieces may have been moved or photographed at a different  
5 location within the geographic area. The wreckage pieces of which the initial  
6 location is uncertain are listed below.

7

8 *Fuselage with a partial window frame*

9 The fuselage, originating from the left hand side of the cockpit, was located at the  
10 side of the road, in the central region of area 2, the village of Petropavlivka.  
11 Residents of the village reported that the wreckage piece had been moved to  
12 expedite the search and recovery mission (Figure 19). The fuselage contained  
13 numerous puncture holes and pitting and showed traces of soot. Frames on the  
14 inner side of the fuselage had been sheared.

15



16

17 *Figure 19 – Handover of the left cockpit window to the DSB by members of the*  
18 *SES. (Source: DSB)*

19 *Fuselage cockpit*


20 A portion of the fuselage, originating from the left hand side of the cockpit, was  
21 identified in a field in the central region of area 2 (the village of Petropavlivka).

22

23 *Centre cockpit window left hand side*

24 One of the layers of the centre window (window number 2) on the left hand side of  
25 the cockpit was collected by local residents. The cockpit windows are made of  
26 multiple layers of glass and plastic. The window had a total of 102 puncture holes

- 1 and marks, varying in size and shape, as seen in Figure 20. Parts of the window  
 2 frame were still attached to the window.  
 3



4 *Figure 20 – Centre cockpit window left hand side (Source: DSB)*

5

6 *The left nose landing gear door*

- 7 Photographic evidence indicated that the left landing gear door had been placed in  
 8 front of the village hall in Petropavlivka, area 2. Nose landing gear related  
 9 components were all identified within or in close proximity of area 3. This included  
 10 the nose landing gear itself and the right nose landing gear door.

11

12 *The rudder horn balance*

- 13 The rudder horn balance was photographed for the first time in area 4 during the  
 14 recovery mission of the Dutch Safety Board in November 2014. Prior to this  
 15 mission, no photographs of this part were available.

16 2.12.2.8 Wreckage not recovered

- 17 As a result of shelling within the geographic area of the accident, the Dutch Safety  
 18 Board was not able to retrieve all identified wreckage pieces during the recovery  
 19 mission in November 2014. The area in which these wreckage pieces were located  
 20 was either not accessible to the Dutch Safety Board or the pieces were no longer  
 21 present at their impact location. Table 13 indicates the wreckage pieces not  
 22 recovered by the Dutch Safety Board.

23

24

25

26

Wreckage piece	Section	Location
Cockpit fuselage top section	Section 41	Area 1
Fuselage top near business class (2 pieces)	Section 41	Area 1
Fuselage left hand side with positive pressure relief valves	Section 43	Area 1
Fuselage with windows and door frame of door 1L	Section 41	Area 2
Fuselage with door frame of door 1R and surrounding fuselage	Section 41	Area 2

1 *Table 13: Wreckage parts not recovered*

2

### 3 **Summary of the wreckage information**

4 Within the geographic area, approximately 50 km<sup>2</sup>, six concentrated areas with  
5 wreckage were identified. The areas were located west and south-west of the  
6 village of Hrabove.

7

8 Area 1 is north of the village of Petropavlivka which is situated 8.8 km west of  
9 Hrabove. Area 2 is the residential area of Petropavlivka and area 3 is southern  
10 corner of the village of Rozsypne, 6.2 km of Hrabove.

11

12 Pieces of wreckage originating from section 41 and 43 of the aeroplane were found  
13 in area 1, 2, and 3. Top portions of the fuselage of section 41 mostly located in area  
14 1. Parts of the fuselage originating from section 43 were mainly found in area 2. The  
15 fuselage of the cockpit and cockpit interior were primarily located in area 3.

16

17 The damage observed in the forward area of the aeroplane indicated that the  
18 aircraft was penetrated by a large number of high energy objects from outside the  
19 aeroplane.

20

21 Area 4, located southwest of Hrabove was adjacent to area 5, located 730 m south  
22 of Hrabove. Area 6 was located in the south-westerly corner of Hrabove.

23

24 The mid and aft sections of the aeroplane were distributed over area 4, 5 and 6.  
25 Area 4 contained mostly pieces of wreckage originating from section 44, 46 and 47.  
26 Both wingtips and both stabilizers were also found in this area. In area 5, pieces of  
27 section 48 were found, including the vertical stabilizer. This area was partially

1 subjected to fire. Both the wings and engines were found in area 6. Parts of the  
2 aeroplane in this area were damaged or consumed by fire.

### 3 **2.13 Medical and pathological information**

#### 4 2.13.1 Flight crew autopsy

5 Identification of the flight crew members was based on clothing and general  
6 appearance during the recovery process. Post-mortem examination was performed  
7 on four possible flight crew members. Given the injury pattern, a full examination  
8 including a body scan and toxicological examination was performed on two flight  
9 crew members designated as body 1 and body 2. The post-mortem examination  
10 revealed that both of the crew members sustained multiple fractures of the skull,  
11 spine, pelvis, ribs, arms and legs. The injury pattern on torso, hands and feet was  
12 consistent with flight crew seating and aeroplane control related injuries at impact  
13 with the ground. In body 2 an aeroplane part, which was identified as belonging to  
14 the right hand side of the aircraft, was found during the post-mortem examination.  
15 The other two possible flight crew members (body 3 and body 4) showed dissimilar  
16 injury patterns and are therefore considered not to have been seated in the front  
17 two flight deck seats.

18  
19 A body scan detected approximately 200 fragments in body 1 and approximately  
20 120 fragments in body 2. In both cases the majority of the fragments were found in  
21 the upper torso and very few fragments were found in the legs and lower torso. A  
22 majority of the fragments were found on the left hand side of body 2. The fragment  
23 scatter for body 1 was more uniform. A number of fragments were sent to the  
24 Netherlands Forensic Institute (NFI) for further examination (See 2.16 Test and  
25 Research) and this examination indicated that all but one of the fragments  
26 examined corresponded to high-energy objects.

27

#### 28 **Summary of injury of the operating flight crew**

29 Both operating pilots sustained multiple injuries associated with high-energy  
30 objects.

31

#### 32 2.13.2 Toxicological examination of flight crew

33 Material was collected for toxicological research from the bodies of the two flight  
34 crew members that were, in all probability, operating the aeroplane at the time of  
35 the accident. The toxicological examination was performed by the NFI.

1 It should be noted that the period of time between the accident and the toxicological  
2 examination being conducted greatly affected the results of that examination.

3

4 For body 1 and body 2 there were no indications of the presence of medicines  
5 (including sedatives), drugs or pesticides in the body. The results also show no  
6 indication of Gamma-Hydroxybutyric acid or a substance from which this acid can  
7 be formed. In both body 1 and body 2 traces of ethanol and metabolites of ethanol  
8 (Ethyl Glucuronide and Ethyl Sulphate) were found in liver and muscle tissue.  
9 These may have been formed, in whole or in part, post-mortem. There is insufficient  
10 research data available on these metabolites in liver and muscle tissue. No blood  
11 was available for toxicological analysis as a result of change post-mortem.

12 On the basis of the results of the toxicological it is not possible to determine when or  
13 how the ethanol was formed.

14

#### 15 **Summary of the toxicological examination**

16 A large number of high-energy objects were found in the operating flight crew's  
17 bodies.

18

19 Traces of medicines, drugs or pesticides were not found either body 1 or body 2.

20

21 Traces of ethanol and its metabolites were found in liver and muscle tissue which  
22 may be formed, in whole or in part, post-mortem. No blood was available for  
23 toxicological analysis as a result of change post-mortem. It is not possible to  
24 determine when or how the ethanol was formed.

25

## 26 **2.14 Fire**

### 27 2.14.1 Pre-accident fire

28 No evidence was found in the wreckage or the recorded data for the ignition or  
29 proliferation of an on-board fire prior to the aeroplane breaking up in flight.

### 30 2.14.2 Post-accident fire

31 Wreckage site number 6 contained evidence of a large fire that consumed much of  
32 the fuselage in the centre section of the aeroplane. The two main landing gear legs  
33 and wing centre box show evidence of fire damage. In addition, the engines show  
34 signs of having been partially exposed to a fire.

35

1 A second, smaller, fire was found to have burned at the location of the Auxiliary  
2 Power Unit at wreckage site 5.

3

#### 4 **Summary**

5 Fires erupted at two locations.

### 6 **2.15 Survival Aspects**

#### 7 2.15.1 First responders

8 The human remains and corpses were initially recovered by the local State  
9 Emergency Service (SES). The organisation received assistance in this from local  
10 fire departments, emergency services, police and local inhabitants.

#### 11 2.15.2 Survivability

12 The accident was not survivable.

13

### 14 **2.16 Tests and research**

15

16 During the investigation, forensic examinations of a large number of foreign objects  
17 were undertaken by the Netherlands Forensic Institute (NFI). This work is described  
18 in the following paragraphs.

#### 19 2.16.1 Forensic examination

20 In the course of the investigation over 500 foreign objects were recovered. In the  
21 wreckage of the aeroplane and in the bodies of the flight crew members a number  
22 of non-aircraft fragments were found that were suspected to be high-energy objects,  
23 or parts of them. A number of these fragments had a distinct butterfly or bow-tie  
24 shape, such as the one shown in the images below, and were magnetic.

25



26 *Figure 21 – Fragments found with butterfly or bow-tie shape. The right hand*  
27 *fragment was found in the body of a flight crew member (Source: NFI)*

1 Forensic examinations were executed on a number of the selected objects as well  
2 as on numerous objects that were taken as reference from the wreckage. The  
3 selection was based on size, shape, mass and ferrous properties. In total 72  
4 selected objects were further examined; 16 foreign objects found in the bodies of  
5 the flight crew members and one passenger, together with 56 foreign objects  
6 recovered from the wreckage.

#### 7 2.16.2 Examinations of the selected objects

8 The origin and the qualitative elemental composition of 72 of the selected objects,  
9 together with 21 reference objects (e.g. aeroplane metal structure, cockpit glass)  
10 were examined by the NFI using a scanning electron microscope and an associated  
11 energy dispersive X-ray analysis system.

12

13 The elemental composition of these objects was determined qualitatively and it was  
14 found that 43 of the recovered objects consisted of unalloyed steel. Other fragments  
15 were found to be non-metallic (coal-slag) or made of stainless steel. On 8 selected  
16 objects of unalloyed steel a glass deposit (consisting of sodium, aluminium, silicon,  
17 oxygen, and zirconium) was found. On other unalloyed steel objects deposits in the  
18 form of molten and re-solidified aluminium were found. Both aluminium and glass  
19 deposits were found in the form of thin layers having a thickness from a few  
20 micrometers to tens of micrometers. On a small number of objects thin layers  
21 containing traces of copper and plastic were found.

22

23 The elemental composition of the aluminium traces found was consistent with the  
24 elemental composition of the aluminium obtained from the aeroplane as reference  
25 material. The investigation did not analyse each trace of aluminium to identify which  
26 aluminium alloys were present.

27

28 The glass deposits present on the surface of the 8 selected objects had an  
29 elemental composition of sodium, aluminium, silicon, oxygen and zirconium. This is  
30 similar to that of cockpit window glass from a reference piece held by the NFI and  
31 with the cockpit glass obtained from the wreckage. The other pieces of glass that  
32 were secured from the wreckage contained no zirconium. It is noted that common  
33 types of glass, such as window glass, car windshields and glass on mobile  
34 telephones do not contain zirconium.

35

36 The chemical composition of 22 selected objects from the bodies of the flight crew  
37 members and one passenger as well as from the wreckage was determined by  
38 means of laser-ablation inductively coupled plasma mass spectrometry. These



1 objects had either a very distinctive shape (e.g. butterfly or bow-tie) or a layer of  
2 deposits was present.

3  
4 A comparison between the objects and their composition was made using a  
5 statistical analysis method; Principal Component Analysis. The analysis showed  
6 that the 22 selected objects from the wreckage and the bodies can be divided in two  
7 distinctive groups. Within such a group, no statistical difference could be determined  
8 between the objects, indicating that the objects originated from the same source. In  
9 other words the objects within a group were made from the same low alloy steel  
10 plate. Two of the analysed objects could not be linked to a distinctive group.

11  
12 The result of the examination was that from the 22 selected objects, 20 objects  
13 were assessed to be high-energy objects; 8 originated from the flight crew and 12  
14 from the wreckage. The other 2 objects of which one was found in a passenger  
15 were not high-energy objects.

#### 16 2.16.3 Explosive residue analysis

17 In addition to these examinations, the NFI took over 500 swab samples on various  
18 locations of the wreckage of the aeroplane and analysed these for explosive  
19 residues.

20  
21 The investigation into the origin of the objects was made more difficult by the  
22 amount of time that the objects had been outside. The possibility of contamination  
23 during transport and by the fact that the wreckage lay in an area of armed conflict  
24 was a concern for the explosive residue analysis.

25  
26 Approximately 30 of the more than 500 swab samples showed traces of two  
27 different explosives; nitro amine (RDX) and tri-nitro toluene (TNT).

#### 28 2.16.4 Results of the NFI's examinations

29 The following results are obtained from the forensic examinations:

- 30 • Some of the over 500 objects recovered had distinctive shapes; cubic and in the  
31 form of a butterfly or bow-tie, and were made of ferrous metal;
- 32 • Of the 22 selected objects found in the bodies of the operating flight crew  
33 members, one passenger and the cockpit area, 20 objects could be divided in  
34 two distinct groups of low alloy steel. Within each group, the objects originate  
35 from the same source. Two objects could not be linked to either group, one  
36 originated from the passenger;
- 37 • The 20 objects that originate from the flight crew members and the cockpit had  
38 aluminium and glass deposits indicating that these fragments originated from  
39 outside the aeroplane and penetrated the cockpit with high energy, and

- 1 • Some of the fragments recovered showed traces of explosive residues.

2

3 **Summary of forensic investigation: high-energy objects**

4 Some of the objects recovered have distinctive shapes; cubic and in the form of a  
5 butterfly or bow-tie and were made of ferrous metal.

6

7 Traces of aluminium and glass were found on 20 objects, both in the bodies of the  
8 flight crew and in the cockpit area of the wreckage. No such objects were found in  
9 the bodies of the passengers.

10

11 The aluminium and glass deposits found indicate that the objects originated from  
12 outside the aeroplane and penetrated the aeroplane with high energy leaving traces  
13 of both aircraft aluminium and cockpit glass.

14

15 Some of the fragments recovered showed traces of explosive residues.

16

17 **2.17 Organisational and management information**

18

19 Factual information and its analysis relating to the decision making processes  
20 around the flight routes is contained in the separate Dutch Safety Board report  
21 entitled "*Flight MH17 and flying over conflict zones*".

22

23 In that report, the following subjects relevant to this accident were investigated:

- 24 • the selection of flight routes by Malaysia Airlines, with particular attention to the  
25 route across Ukraine;
- 26 • the oversight by the Malaysian authorities, and
- 27 • the management of airspace in Ukraine, with particular attention to the restriction  
28 of airspace made by the Ukrainian authorities.

29 **2.18 Additional information**

30

31 This paragraph contains a number of relevant subjects that have not been  
32 addressed elsewhere in Section 2. These relate to:

- 33 • a description to two different aeroplane systems; cabin pressurisation and cabin  
34 emergency oxygen system;
- 35 • background information on possible external sources of damage, and
- 36 • the preventative actions taken following the accident.

1  
2 The weather is consistent with storms around which it is reasonably expected that a  
3 flight crew would request to circumnavigate.

4  
5 With the exception of a deviation requested by the flight crew to avoid bad weather,  
6 the aeroplane followed the planned route, airway L980 across Ukraine, not leaving  
7 the width of the airway by more than approximately 1.5 NM.

### 8 **3.3 The moment of high-energy object penetration**

9

#### 10 3.3.1 Aeroplane data recorders

11 According to the information in Section 2.11, the following Flight Data Recorder  
12 parameters as recorded 13.20:03 (15.20:03 CET) were:

- 13 • Aeroplane position
  - 14 ○ Latitude: 48.12715 N
  - 15 ○ Longitude: 38.52630538 E
  - 16 ○ Pressure<sup>10</sup> altitude: 32,998 feet
  - 17 ○ Indicated airspeed: 293 knots
  - 18 ○ Magnetic Heading: 115 °
  - 19 ○ Drift angle: -4 degrees
- 20 • Weather
  - 21 ○ Wind direction: 219 °
  - 22 ○ Wind speed: 36 knots
  - 23 ○ Static temperature: -44 °C
  - 24 ○ Air temperature: -12/-13 °C


25 Small variations in the data are possible due to differences in resolution from the  
26 various data sources.

27  
28 Detailed analysis of the Cockpit Voice Recorder for the last 20 milliseconds of the  
29 recording at 13.20:03 (15.20:03 CET) as described in paragraph 2.11.2 showed that  
30 two peaks of sound were identified in this timeframe. Using specialised audio  
31 recording analyses software a graphical representation of the sound over time, its  
32 waveform, could be established. The wave form analysis will assist in determining  
33 the signal's characteristics; for example, time duration and energy.

34  
35 The first sound peak had a duration of 2.1 milliseconds and the signal was recorded  
36 on the CAM channel only. As no other channels recorded this signal the direction of  
37 the signal could not be established. Wave spectrum analysis suggests that the

<sup>10</sup> Altimeter set to the standard pressure of 1013.25 hPa

1 sound peak is representative for an 'electrical spike' as it shows the form of an  
2 electro-magnetic pulse that could have been caused by static discharge, or similar.  
3  
4 The time difference between the first and second sound peak was determined to be  
5 2.3 milliseconds. The second peak had a duration of 2.3 milliseconds and was  
6 recorded by all 4 channels, but not all at the same time as some recordings had a  
7 different timestamp. The phase difference between the channels shows that the  
8 sound was recorded by the CAM and P1 microphones first, then the P2 one before,  
9 lastly, the Observer microphone. The wave spectrum is representative for a sound  
10 wave. This difference in time shows that the sound wave originated outside the  
11 aeroplane starting from a position above the left hand side of the cockpit,  
12 propagating from front to aft.  
13  
14 It is concluded that the event was highly energetic in nature based on the short time  
15 duration of the event.  
16  
17 Signal triangulation was used to determine the origin of the second sound peak  
18 recorded on the Cockpit Voice Recorder. It was determined that the sound  
19 originated outside the aeroplane on the left hand side. The fact that the microphone  
20 cap of the CAM channel was missing did not influence the calculation. However,  
21 during the investigation, the Safety Board noted that the sound peaks are of such  
22 short time duration that any minor differences in recording will cause the signal  
23 triangulation to be erroneous. For example, signal latency (refers to a short period  
24 of delay between when an audio signal enters and when it emerges from a system)  
25 can be influenced by the Cockpit Voice Recorder microphone wiring. When one  
26 microphone wire is 'longer' compared to others this may affect the time for the  
27 signal to reach the Cockpit Voice Recorder. Nonetheless, the signal triangulation is  
28 consistent with the impact damage on the left side of the cockpit. Therefore it is  
29 likely that the origin of the sound peak recorded on the Cockpit Voice Recorder is a  
30 recording of the detonation of the warhead outside the cockpit.  
31  
32 The point of detonation, the impact damage and the type of warhead are analysed  
33 elsewhere in Section 3 of this report.  
34



1  
2 *Figure 24 – second sound peak – graphic representation*

3  
4  
5 The poor sound quality on the CAM channel noted during the investigation was  
6 probably due to the missing microphone cap from the CAM. The fact that the  
7 microphone cap was missing was noted on the deferred defects list for the subject  
8 aeroplane.

9  
10 The Flight Data Recorder data as described in paragraph 2.11.3 and Appendix K  
11 was examined to try and identify any acceleration associated with the sound wave  
12 that had been recorded on the Cockpit Voice Recorder. The following three axes of  
13 acceleration with their sampling rate are recorded on the Flight Data Recorder:

- 14
- 15 • Longitudinal acceleration: 4 times a second (4 Hz)
  - 16 • Vertical acceleration: 8 times a second (8 Hz)
  - 17 • Lateral acceleration: 4 times a second (4 Hz)
- 18  
19  
20  
21  
22  
23  
24  
25  
26

1 The damaged area of the forward pressure bulkhead has very limited apparent  
2 evidence of high-energy object damage on the bulkhead.

3

4 It is noted that the damage to the cockpit appears to be centred on the left hand  
5 forward side, near the left hand seat position, where there is evidence of blast  
6 deposit, direct pressure damage, and extensive fragmentation damage. The  
7 apparent fragment damage pattern extends from the captain's seat from the left  
8 forward to the right hand aft side of the cockpit, and appears to be sharply bounded.  
9 This matches the damage found on the outside parts of the nose of the aeroplane.

10

11 A number of parts are covered in soot, an indication of explosive residue on the  
12 aeroplane. 'Sooting' is noted on the inside of the right hand cockpit windows 2 and 3  
13 and on parts of the outside left hand cockpit fuselage.

14

15 The panel, a part of the fuselage to the right of the nose landing gear, between  
16 STA250 and STA330, that shows damage considered to be 'dishing'; a form of  
17 damage associated with the effects of blast. Figure 23 shows that the panels' skin  
18 between the structural elements is deformed. The reason that an adjacent part of  
19 the nose gear door (STA184) had no detectable blast damage is that this part is  
20 made of a honeycomb construction that is highly resistant to the effects of excess  
21 pressure.

### 22 3.11.3 Failure analysis

23 Paragraphs 3.11.3.1 to 3.11.3.7 contain an analysis of the way the aeroplane's  
24 structure failed after the impact of the high-energy objects. A number of definitions  
25 of the types of failure displayed on the wreckage parts; essential to a better  
26 understanding of the analysis, have been included in Appendix N.

#### 27 3.11.3.1 General

28 Analysis indicates that, following the separation of the cockpit from the fuselage, the  
29 cockpit descended with a steep angle. The distance between the last known  
30 position of the aeroplane, recorded on the Flight Data Recorder, and the location of  
31 the cockpit, including the nose wheel bay is about 2.3 km. There is general  
32 evidence of overload break up, deformation by aerodynamic forces, impact damage  
33 such as crushing, folding and bending, and in some cases burning.

34


35 Based on paragraph 2.12.2, examination of the wreckage parts of the fuselage  
36 stiffened skin structures and their fracture surfaces has revealed the following  
37 observations (see Figure 41):

- 1 • The upper left cockpit structure is missing, but the available pieces indicate  
2 penetration holes. Starting from the cockpit window a rupture runs downward  
3 toward to the passenger floor (stringer L27) at STA236.5.1.
- 4 • The upper right cockpit section appears intact and exhibits a primary fracture  
5 approximately along STA236.52. This fracture runs towards the passenger floor  
6 (stringer 27R). This fracture seems to align with fractures observed with  
7 photographic evidence obtained from Ukraine where panels contain failures  
8 along STA236.50. These fractures develop approximately at the level of the  
9 passenger floor backward parallel to the stringers 273L and 274R.
- 10 • Another rupture has been observed at the circumferential joint at STA655.50  
11 which seems to run almost entirely in the circumference of the fuselage with  
12 intersections with the horizontal fractures along the passenger floors at STA655.
- 13 • This circumferential fracture follows STA655 straight to the passenger floor in a  
14 predominantly tensile mode. Below the passenger floor the direction of the  
15 fracture at the left hand side initially continues towards the longitudinal joint at  
16 stringer 34L6 after which its path is unclear. The fracture at the right hand side  
17 seems to deviate from its path, heading slightly backward until it reaches the  
18 longitudinal joint at stringer 34R after which it turns forward towards the bottom  
19 of the fuselage panel 7.
- 20 • Although certain pieces of the lower left structure were missing, the two lower  
21 fuselage panels before and aft of STA613 indicate that this general rupture at  
22 the location of the circumferential joint has continued entirely along the full  
23 circumference of the fuselage. This rupture has led to separation of the forward  
24 fuselage from the remainder of the fuselage. The outward bending of the lower  
25 fuselage panel aft of STA613.80 indicates that final separation of the forward  
26 fuselage section occurred at the bottom of the fuselage.

27

28 For the forward fuselage section up to about STA1032 a digital two-dimensional  
29 reconstruction was made. The approach was to first generate a grid consisting of all  
30 fuselage frames and stiffeners positions. Subsequently, the green-screen photos  
31 that were made of structural parts were positioned onto the grid at the right scale  
32 and orientation. The resulting final image is shown in Figure 52.

33



1  
 2 *Figure 52 – Grid reconstruction of the outside skin of the forward fuselage. Overlaid*  
 3 *outline indicates approximate boundary of the piece prior to dismantling for transport*  
 4 *to the Netherlands. Colour indicates wreckage site.*

5  
 6 *Note:*  
 7 *Unrecovered pieces are highlighted in blue and were reconstructed based on*  
 8 *accident scene photos. Piece A indicates a piece of skin attached to the nose*  
 9 *landing gear bay for which photographs are not available. All show tearing and*  
 10 *peeling damage. Close examination of the wreckage parts available revealed no*  
 11 *evidence of pre-existing structural faults (such as fatigue, corrosion or mechanical*  
 12 *damage) that could have contributed to the in-flight break-up.*

13  
 14 For the forward fuselage section it was verified that the forward cargo door was still  
 15 closed.


16  
 17 Examination of the available wreckage pieces forward of STA888 revealed several  
 18 features that manifested during break-up of this section. These features include:

- 19
- 20 • Tensile overload failure;
  - 21 • Isolated bending/peeling of wreckage pieces;
  - 22 • Regions of skin/sub-structure separation, and
  - 23 • Gross buckling damage.

24 The overall distribution of these observed features is illustrated on the  
 25 reconstruction grid in Figure 53. It is noted that some of these features are indicated




- 1 for wreckage pieces not available to the investigation team for direct inspection.  
 2 Only features that were clearly visible in wreckage site photographs have been  
 3 included for those unavailable parts.



4  
 5 *Figure 53 – Overview of the forward fuselage wreckage parts indicating major*  
 6 *break-up features*

- 7  
 8 Each of these features will be briefly described and illustrated with representative  
 9 photographic evidence.

- 10  
 11 An example of tensile overload failure this type of fracture is given in Figure 54.  
 12



13  
 14 *Figure 54 – Typical case of pure tensile overload failure; straight cracks in net-*  
 15 *section, paint cracks aligned with skin crack, stiffener coupling failure at the first*  
 16 *fastener*

This is a copy of the draft Final Report of this investigation intended solely for consultation as per ICAO Annex 13, paragraph 6.3. It shall not be released to or communicated with parties other than those to whom the report is addressed.

1  
2  
3  
4  
5  
6  
7  
8  
9  
10  
11  
12  
13  
14  
15  
16  
17  
18  
19  
20  
21  
22  
23  
24  
25  
26  
27  
28  
29  
30  
31  
32  
33  
34  
35  
36

A representative example of isolated bending/peeling is given in Figure 55. Note, the arrow in the figure indicates the direction of peeling.



Figure 55 – Example of bending/peeling at a fracture line located along STA655 associated with the final separation between two pieces of wreckage.

A representative example of skin/sub-structure separation is given in Figure 56.




Figure 56 – Example of skin/sub-structure separation in the nose section immediately forward of the door 1R.

A representative example of gross buckling is given in Figure 57.



1  
2  
3  
4  
Figure 57 – Example of gross buckling of the lower fuselage skin panel near STA487.



5  
6  
7  
8  
9  
Figure 58 – Overview of forward fuselage wreckage parts indicating the modes of fracture in detail

10 Based on the different locations of wreckage parts found, it was concluded that the  
11 separation between the centre part and the rear part of the fuselage occurred at  
12 approximately fuselage station STA1546.5. This location coincides with the aft door  
13 frame of passenger doors 3L and 3R.

14  
15 A study of the fuselage parts, available in the data base, showed that a large skin  
16 panel on the left upper side of the fuselage, extending from half way the main

1 landing gear wheel bay in front of doors 3L & 3R to about 1.5 meters aft of door 3L  
2 & 3R, was found at the same location as the parts of the rear fuselage (in wreckage  
3 area number 4). This part probably separated just before the fuselage rear part  
4 broke away. As this part separated, the section at the doors was weakened. The  
5 weakened fuselage section then broke and the rear part separated. Top and bottom  
6 panels were missing on the left hand side.

7

8 On the right hand side a larger severe deformed panel was available, running from  
9 the top, about stiffener 11R, to about stiffener 40R at the bottom.

10

11 The fracture surfaces that were deemed to interface with the panels in the main  
12 wreckage site were examined.

13 3.11.3.2 Fuselage left hand side

14 Only a panel of the side shell has been found and was examined. For the left panel,  
15 this concerns fractures from the upper right door corner of passenger door 3L  
16 upward, and fracture from the lower right corner downward. Both fractures together  
17 align into a vertical fracture. Both fracture surfaces exhibit fractures consistent with  
18 tensile overstress fracture.

19



20

21 *Figure 59 – Tensile overstress fracture at the upper right door corner of passenger*  
22 *door 3L*  
23



1  
2 *Figure 60 – Tensile overstress fracture at the lower right door corner of passenger*  
3 *door 3L*

4 3.11.3.3 Fuselage right hand side

5 At the right hand side, a single fracture starting at the lower left corner of the  
6 passenger door 3R was present and has been examined. In figure 61, the lower  
7 corner shows an overstress fracture mainly tensile (about 45 degrees with the  
8 horizontal combined with some outward bending).  
9



10  
11 *Figure 61 – Overstress fracture at the inside of the lower left door corner of*  
12 *passenger door 3R (Source: DSB)*

13  
14 *Upper door corner 3R*

15 Figure 62 shows the structure aft of door 3R. The skin plus stiffeners far above the  
16 door level show a tensile fracture. The fracture near the top of the door is more  
17 complicated. It shows peeling of the skin combined with a complicated fracture of  
18 the door frame adjacent to the door just above the door.



1  
2 *Figure 62 – Tensile overstress fracture at the outside of the lower left door corner of*  
3 *door 3R (source: DSB)*

4  
5 *Lower door corner 3R*

6 The fracture at the door corner is consistent with a tensile loading direction upper  
7 left to lower right plus some out of plane bending. The fracture appears to be a  
8 complex fracture surface consistent with tensile overstress, of which the load case  
9 is not evident. The skin fracture surface directs in the vertical and under an angle of  
10 45 degrees heading aft, with out-of-plane deformations of the sheet material,  
11 together with fracture of the frame at STA1546.5. This frame fracture is, it was  
12 concluded, the result of a combination of tension and bending in a direction  
13 opposite to the frame curvature. The determination of the direction is based on the  
14 alignment of the fracture surface.

15  
16 In the area investigated, no repairs were observed. Traces of fatigue or corrosion  
17 were not found.

18



19  
20 *Figure 63 – Severely deformed fuselage structure aft of passenger door 3R,*  
21 *including aft cargo door surrounding structure (source: DSB)*

22  
23

1 3.11.3.4 Cockpit and front fuselage

2 The rupture along the circumferential joint at STA655 appears to be consistent with  
3 a downward bending moment applied unto the cockpit section causing tension in  
4 the upper fuselage and compression in the lowest shells. The fracture surfaces in  
5 the upper and side shells are consistent with tensile overstress fracture, while the  
6 lowest shells exhibit indications of compression and bending, like for example  
7 stringer crippling.

8

9 The forward fuselage section has separated approximately along the passenger  
10 floor into a cockpit section connected to the lower fuselage sections until STA655,  
11 and upper fuselage sections above stringers 27L and 27R.

12

13 The upper part between frame stations STA246 and STA655 was found at a  
14 different site near Petropavlivka, whilst the cockpit section, mostly attached to the  
15 lower fuselage sections, was found near Rozsypne. The upper fuselage sections  
16 have not been retrieved and could therefore not been examined, while most of the  
17 structure of the cockpit and lower fuselage section have been found and examined  
18 for the fracture patterns and fracture surfaces.

19

20 After the full rupture of the forward fuselage at STA655, the remainder of the  
21 fuselage in front of the wing seems to have developed fractures in longitudinal  
22 direction at locations between stringer R4 and R79, and near stringer R2910 and  
23 R3411 (longitudinal joint). At the left hand side a fracture has developed along  
24 stringer L2912 with evidence of out-of-plane deformation of the skin. These fracture  
25 orientations seem consistent with a radial opening of the fuselage. Many cases of  
26 peeling and tensile fracture have been observed; the longitudinal joint at R34 failed  
27 by separation rather than shear, and the skin near STA825 separated in tension  
28 from the back-up structure.

29

30 All evidence and ruptured fuselage panels observed was limited to the area before  
31 STA951.

32

33 Based on the position that the wreckage was found in, it has been determined that  
34 the centre part of the aeroplane landed upside down facing aft. Given the positions  
35 of the engines and the parts of the wings, this part tumbled forward during its  
36 descent. It is noted that this conclusion was confirmed on location after NBAAI  
37 investigators had come to a similar conclusion on 18 July 2014 using a  
38 photographic reconstruction.

1 3.11.3.5 Rear fuselage


2 The separation of the rear fuselage probably took place after the separation of a  
3 large skin panel on the left upper side of the fuselage, (data base number 40)  
4 extending from half way the main landing gear wheel bay to about 1.5 meters aft of  
5 door 3L & 3R) and possible of other upper fuselage parts at that area, not  
6 recovered, immediately followed by the separation caused by failure of the  
7 remainder of the fuselage at STA1546.5.

8

9 This last separation was caused by a bending moment to the right, as seen from the  
10 direction of flight, that resulted in a shear load acting on the damaged, incomplete  
11 aft fuselage at STA1546.6.

12

13 The distortion to the parts of the vertical stabilizer (indicated by two arrows in Figure  
14 64) provides direct evidence of the overload that the aeroplane was subjected to  
15 during its fall. The way that the parts are bent shows that these forces were from the  
16 side, pushing the vertical stabilizer over to the right, as seen from the direction of  
17 flight.



18

19 *Figure 64 – Overload failure of the vertical stabilizer (Source: DSB)*

20 3.11.3.6 Rear pressure bulkhead

21 The parts available belonging to the rear pressure bulkhead as discussed in  
22 2.12.2.4 were examined. The fractures in circumferential direction followed the  
23 intersection with either the fuselage, or at the stiffening straps. These fractures are  
24 predominantly tensile overstress fractures in the net section.

25



1 In addition, circumferential fractures were observed at the centre element of the  
2 dome. Also these fracture surfaces are consistent with overstress fractures as result  
3 of combinations of tension and out of plane bending.

4  
5 In radial direction fractures were observed also consistent with tensile overstress  
6 fractures. These fractures follow the fastener row underneath the radial stiffeners.  
7 The plate in the vicinity of the fracture, as well as the stiffener, exhibits significant  
8 deformations.

9  
10 At some locations along the connection between pressure bulkhead and fuselage  
11 the fractures deviated from their circumferential path, towards adjacent stiffening  
12 straps. A few irregular fractures were also observed.

13  
14 The fractures observed in the bulkhead were consistent with tensile overstress,  
15 caused either a pressure difference or a disintegrating fuselage structure, where a  
16 relatively flexible, thin, walled dome is pulled apart by the surrounding structure.

17  
18 There are indications that there was no sudden failure by overpressure of the rear  
19 pressure bulk head:

- 20 • No damage or deformation consistent with an overpressure in the fuselage tail  
21 cone structure.
- 22 • Rear pressure bulkhead parts and parts of surrounding fuselages structure were  
23 found at the rear end of the debris pattern, not at the beginning of it.

24  
25 In the bulkhead dome no repairs were observed. Traces of fatigue or corrosion were  
26 not found.

### 27 3.11.3.7 Wings and empennage

28 A review of the two wingtips and the horizontal stabilizers indicated the direction of  
29 the failure. In the case of the wingtips, the stringers and ribs on both sides showed  
30 signs of having been torn backwards.

31  
32 The two horizontal stabilizers both showed evidence of having failed after bending  
33 upwards. On the left stabilizer bolts and brackets exhibited the signs of the  
34 bending. The evidence of upwards bending on the right stabilizer was seen in the  
35 way that the stringers had been bent. The extensive use of composite materials in  
36 the stabilizers made further analysis impossible.

37  
38 The high-energy object penetration on the inboard flaperon on the left wing was  
39 analysed as part of the analysis in the effects and origin of the high-energy objects.

## 1 3.11.3.8 Negative pressure relief valve

2 A pressure relief valve from the right forward side of the aeroplane was found  
3 opened into the extreme position. As the negative pressure difference over the  
4 pressure relief valve is normally relatively small and builds up gradually, the  
5 observed damage (See Appendix O) has to be the result of an unusual condition.  
6 Because the valve is designed for the relief of small pressure differences, it cannot  
7 be ruled out that the damage might have been the effect of a shock wave, caused  
8 by the external detonation, which occurred on the left hand side of the aeroplane.  
9 However, the relief valve found was from the right side of the fuselage. It might have  
10 come into the extreme position due to ground impact or due to transportation and  
11 handling.

## 12 3.11.3.9 Main landing gear

13 As evidenced by the recovered main landing gear assemblies there were no intact  
14 lock links to secure the side/drag braces; both were sheared off. In addition, in an  
15 in-flight breakup, air loads from the fall, collision with other debris, ground impact  
16 and disturbance during recovery/transportation, could all randomise the motion of  
17 unsecured side/drag braces. The Flight Data Recorder data indicated that the  
18 landing gear was in the retracted position at the last recorded position of the  
19 aeroplane. Therefore it is likely that landing gear extension of one of the gears is a  
20 result of the in-flight break-up and/or the following ground impact.  
21

22 **Findings**

23 The failure sequence is consistent with the failure initiating near the left hand side of  
24 the cockpit.  
25

26 There was an almost simultaneous separation between the cockpit with the lower  
27 fuselage and upper fuselage at stringer 27 from nose to Station 655 and the heavily  
28 damaged cockpit with lower and upper forward fuselage at Station 655, followed by  
29 the fuselage between STA655 and STA951 opening in a radial fashion and  
30 separating.  
31

32 The fracture of the rear fuselage section near doors 3L and 3R at STA1546.5 (to  
33 the rear of the wing) indicates a high lateral bending moment to the right on the  
34 fuselage. The fractures in the rear pressure bulkhead are consistent with overstress  
35 fractures.  
36

37 The wingtips both failed, tearing rearward. After this, the stabilizer and fin separate  
38 from the rear fuselage again with a high lateral bending moment to the right.  
39

1 It is likely that landing gear extension of one of the gears is a result of the in-flight  
2 break-up and/or the following ground impact.

3  
4 The investigation did not indicate the presence of pre-existing damage, such as  
5 fatigue, corrosion or inadequately performed repairs.

#### 6 7 3.11.4 In-flight break-up scenario

8 Following the separation of the cockpit from the fuselage, the cockpit descended  
9 with a steep angle. The horizontal distance between the last known position of the  
10 aeroplane, recorded on the FDR, and the location of the cockpit, including the nose  
11 wheel bay is about 2.3 km.

12  
13 The distribution of the aeroplane wreckage parts over a large area indicates that the  
14 aeroplane broke up in the air. The forward parts of the aeroplane were found  
15 closest to the last Flight Data Recorder point, indicating that these parts broke off  
16 from the aeroplane first. Since the centre and aft parts of the aeroplane were  
17 discovered significantly further to the east, this indicated that these parts continued  
18 in a down and forward trajectory and disintegrated later.

19  
20 The failure analysis of the aeroplane's structure, as described in paragraph 3.11  
21 shows a sequence whereby the aeroplane's fuselage separates at STA655; a point  
22 towards the rear of the business class section of the aeroplane. A second structural  
23 failure occurs at STA1546.5 behind the wing, causing the rear fuselage and tail to  
24 separate. The three parts of the aeroplane fell in different locations. The debris  
25 locations of the remainder of the aircraft (near Hrabove) cannot be explained by a  
26 'simple' ballistic trajectory, suggesting that part still had some lift and thus continued  
27 'flying' for some time.

#### 28 29 **Aerodynamic stability**

30 If one flies straight and level in an aeroplane, with the forces trimmed out and the  
31 pilot makes no control inputs, the aeroplane will maintain a constant path through  
32 the air (assuming still air). Moving the controls to a new positioning and holding  
33 them there will cause the aeroplane to deviate slowly from the straight and level  
34 flight. If only the ailerons are moved, the aeroplane starts slowly to bank and will  
35 turn to the left or right as commanded. As it banks, it also slips so as to not only  
36 deviate from its flight path but also it will start to descend. These movements

1 intensify over time. The bank angle and the roll angle will increase over time whilst  
2 the radius of the turn will decrease over the same time; the aeroplane flies in a  
3 tighter and ever steeper spiral. The slipping flight causes lateral loads on the vertical  
4 stabilizer and on the fuselage. This lateral load increases over time. Without  
5 correction by the pilot, this continues until structural failure of the aeroplane in flight  
6 or impact with the ground.

7  
8 When the fuselage forward of STA888 separated from the aeroplane it caused the  
9 centre of gravity of the rest of the aeroplane to move rearward. The influence of the  
10 moment around the aeroplane's lateral axis is considered to be relatively small.  
11 There were no more control inputs from the flight crew possible and the control  
12 surfaces would have been in their neutral positions. As a result of this, the  
13 behaviour of the aeroplane, rotations round the three axes and thus the flight path,  
14 were determined by the dynamic stability of the aircraft.

15  
16 The flight path with respect to the ground will depend on the wind speed and  
17 direction at the heights between the start of the event and impact with the ground. In  
18 a situation without control inputs, the behaviour of the aeroplane is determined by  
19 the dynamic stability of the aeroplane. In such a situation, the behaviour of the  
20 aeroplane's movement can be periodic, known as Dutch Roll, or be a-periodic;  
21 *spiral mode*. The spiral mode is caused by the fact that, for most aeroplanes, the  
22 static directional stability is larger than the absolute value of the static roll stability.

23  
24 In the case of the accident aeroplane, a bank angle slowly increased after the  
25 separation of the cockpit, causing the side slip angle to increase. From the positions  
26 of the wreckage on the ground, it is certain that the aeroplane turned to the left in  
27 slowly following an increasingly curved path.

28  
29 Due to the tightening spiral and slip angle, the lateral load on the vertical fin and the  
30 fuselage increased. This loading caused an increasing bending moment to the right  
31 on the fuselage behind the wing, that eventually resulted in a structural failure of the  
32 fuselage by a vertical bending moment. The failure occurred at a point close to the  
33 passenger doors, 3L and 3R. As all of these parts aft of STA888 were found on the  
34 ground closely spaced, it can be concluded that the structural failure described here  
35 happened at a relatively low altitude.

36  
37 The examination of the wreckage distribution also shows that the final heading of  
38 the wreckage was to the north. This suggests that the final part of the descent  
39 trajectory had a decreasing radius. This is consistent with a change to the dynamics  
40 of the wreckage as the tail separates.

1

2 After the separation at STA1546.5, passenger doors 3L and 3R, the wing with the  
3 centre fuselage section, without the tail plane, is longitudinally unstable but the roll  
4 stability is positive. In this situation the centre of pressure is behind the centre of  
5 gravity, it becomes longitudinally unstable, causing it to tumble forward. The rotation  
6 rate and the number of rotations is unknown, but it is expected to be few due to the  
7 low altitude.

8

9 The centre section was found upside down with few indications on the ground of  
10 horizontal movement having struck the ground in a nearly horizontal attitude, with a  
11 large descent angle. This is a consequence of the forward rotation described above.  
12 moving in rearward direction.

13

14 A part of the fuselage just in front of door 3R was found under the aeroplane's keel  
15 beam structure and a part of the lower fuselage, just in front of the centre wing, was  
16 found just ahead of the main wreck. This is consistent with an upside down centre  
17 section moving in rearward direction when hitting the ground.

18

19 It is not possible to accurately determine the time between the start of the break-up  
20 and the impact with the ground. The wreckage distribution suggests that the forward  
21 part of the aeroplane is unlikely to have fallen at the same speed as the remainder  
22 of the aeroplane. Taking into account the descent speed and the path that the  
23 remainder of the aeroplane followed (see explanation on aerodynamic stability  
24 above), the centre and rear parts of the aeroplane were estimated to have taken  
25 about a minute and a half to reach the ground. Other lighter parts (e.g. cargo and  
26 baggage) will have taken longer to reach the ground.

27

## 28 Findings

29 The debris found near wreckage area 2 and wreckage area 3 is consistent with a  
30 rapid separation of the cockpit section and numerous smaller parts of the front  
31 section of the aircraft, that started at the last recorded aircraft location or slightly  
32 thereafter.

33

34 The centre and rear part of the fuselage remained, initially, intact, gliding  
35 aerodynamically and came to rest about 8.5 kilometres to the east. The centre  
36 section travelled the further than the rear part of the fuselage.

37

38 The time between the start of the break-up and the impact with the ground cannot  
39 be accurately determined. Taking into account the descent speed and the path that

1 the remainder of the aeroplane followed, the centre and rear parts of the aeroplane  
2 were estimated to have taken between 1 – 1.5 minutes to reach the ground. Other,  
3 lighter parts, will have taken longer.

4

#### 5 3.11.5 Passenger oxygen system

6 When the cabin of the aeroplane depressurised, the cabin altitude of 13,500 feet  
7 was exceeded, which normally deploys the passenger oxygen masks. However, no  
8 system data was found to confirm this, because it had not been stored in the  
9 equipment recovered and the recorder that had the capability to store such  
10 information was not recovered. FDR data shows that the cabin pressure altitude is  
11 recorded as being 4,800 feet during cruise up to the moment that the recording  
12 stopped at 13:20:03 (15:20:03 CET) (see Appendix K).

13

14 According to the manufacturer, when depressurisation occurs the deployment of the  
15 masks may take a few seconds. Since electrical power to the Cockpit Voice  
16 Recorder and Flight Data Recorder was lost almost instantly after the penetration by  
17 the high-energy objects, Electrical power to the solenoid was probably also lost  
18 immediately making it unlikely the passenger emergency oxygen masks were  
19 deployed. Nevertheless, the solenoid switches might have been moved into the  
20 unlocked position as a result of the forces on them during the accident or due to  
21 impact with the ground.

22

23 A visual examination of four generators recovered from the wreckage showed that  
24 the metal wires that normally initiate the production of oxygen had been pulled out  
25 and that the indicator stripe on the oxygen generators showed a black stripe  
26 indicator suggesting that they had been 'fired', producing oxygen, see below figure  
27 65. Some masks may have deployed as a result of the aeroplane's disintegration  
28 and all may have been exposed to strong winds or other dynamic forces during the  
29 fall of the aeroplane. Additionally, as it requires only a small force of only a few  
30 Newton (Federal Aviation Administration specification TSO-C64 refers) to remove  
31 the firing pin from the oxygen generator, it is conceivable that the oxygen  
32 generators were fired as a result of either the dynamic forces during the fall or from  
33 the impact with the ground.

34

1

## 4 CONCLUSIONS

2 The Dutch Safety Board determined the following conclusions in relation to the  
3 accident to flight MH17 on 17 July 2014.

### 4 4.1 Cause

5

6 The Dutch Safety Board determined the following main conclusions regarding the  
7 cause of the accident to flight MH17:

- 8 • On 17 July 2014, a Boeing 777-200 with registration 9M-MRD, operated by a  
9 licensed and qualified flight crew, was in cruise flight at flight level 330 close to  
10 the Ukrainian / Russian Federation border and under the control of Ukrainian Air  
11 Traffic Control.
- 12 • At 13.20:03 (15.20:03 CET) the structural integrity of the airworthy aeroplane  
13 was compromised and the flight crew were immediately incapacitated by the  
14 detonation of a 9M314-model warhead containing pre-formed fragments.
- 15 • The 9M314-model warhead carried by a 9M38-series missile was launched  
16 from a Buk, Buk-M1 or Buk-M1-2 surface-to-air missile system in an area south  
17 of Snizhne, Ukraine.
- 18 • The aeroplane consequently broke up in flight and fell to the ground near the  
19 town of Hrabove, Ukraine. All 298 occupants lost their lives.
- 20 • Other scenarios that could have led to the disintegration of the aeroplane were  
21 considered, analysed and excluded based on the evidence available.

### 22 4.2 Supporting conclusions

23 The Safety Board's investigation's main conclusion is supported by the following  
24 material.

- 25 1. *Moment of the in-flight break-up* The establishment of the moment of  
26 the in-flight break-up of the aeroplane is supported by the following findings:
  - 27 a. The Cockpit Voice Recorder and Flight Data Recorder stopped abruptly  
28 at 13.20:03 (15.20:03 CET) because the power supply was interrupted.
  - 29 b. The automatic Emergency Locator Transmitter activated within 2  
30 seconds of the Cockpit Voice Recorder and Flight Data Recorder  
31 ceasing to record.
  - 32 c. The raw surveillance radar data from the Ukrainian Air Navigation  
33 Service Provider and the radar screen video replay from the Russian  
34 Federation's Air Navigation Service Provider showed that flight MH17

- 1 was in straight and level flight at FL330 until 13.20:03 (15.20:03 CET)  
2 as it crossed the eastern part of Ukraine.
- 3 d. The raw data from Ukrainian Air Navigation Service Provider further  
4 showed that flight MH17 was not transmitting any secondary  
5 surveillance data from 13.20:03 (15.20:03 CET) onwards.
- 6 e. The Russian Federation's Air Navigation Service Provider radar screen  
7 video replay of the combined primary and secondary radar data showed  
8 target tracks from the aeroplane from 13.20:03 (15.20:03 CET) onward  
9 which were the result of coasting and of falling debris.
- 10
- 11 2. *Sound peak* The Cockpit Voice Recorder recorded a 2.3 milliseconds sound  
12 peak that originated outside the aeroplane from a position above the left side  
13 of the cockpit, propagating from front to aft. The signal triangulation was  
14 consistent with the impact of a warhead detonating outside and to the left of  
15 the cockpit.
- 16
- 17 3. *No other aeroplanes* There was no evidence of other aircraft, civilian or  
18 military, in the direct vicinity of flight MH17. According to radar data only three  
19 other aeroplanes were in Dnipropetrovsk Control Sector 4 at the time of the  
20 accident, all commercial air transport category aeroplanes. Two were flying  
21 eastbound one was flying westbound. All were under control of Dnipro Radar.  
22 At 13.20 (15.20 CET) the distance between the closest of these aeroplanes  
23 and flight MH17 was 33 km.
- 24
- 25 4. *High-energy object damage* The damage observed on the forward  
26 fuselage and cockpit area of the aeroplane indicates that there were multiple  
27 impacts from a large number of high-energy objects from outside the  
28 aeroplane. This caused sufficient structural damage to lead to an in-flight  
29 break-up. The pattern of damage observed to the forward fuselage and cockpit  
30 area of the aeroplane was not consistent with the damage that would be  
31 expected from any known failure mode of the aeroplane, its engines or  
32 systems.
- 33
- 34 5. *Fragments from one location* The aeroplane was struck by a large  
35 number of small objects with different shapes and sizes; cubic and in the form  
36 of a butterfly or bow-tie, moving at high velocity. The direction of both the  
37 penetrating and the non-penetrating fragments originated from a single  
38 location outside left and above the cockpit. The fragments caused damage to  
39 the left side of the cockpit, the left engine cowling lip ring and the left wing tip.  
40



- 1 6. *Damage pattern* The location, shape and boundaries of the damage to the  
2 wreckage of flight MH17 and the number and density of hits on the wreckage  
3 was consistent with fragmentation spray pattern damage of pre-formed  
4 fragments from different shapes and sizes in a 9N314-model warhead carried  
5 on the 9M38-series of missiles and installed on the Buk, Buk-M1 or Buk-M1-2  
6 surface to air missile system.  
7
- 8 7. *Pre-formed fragments* High-energy objects found in the aeroplane and  
9 the bodies of the flight crew were mainly of unalloyed steel some of which  
10 showed evidence of having passed through the aeroplane's exterior surface  
11 and cockpit windows. Some of the objects showed traces of explosive  
12 residues. There were no high-energy objects found in the bodies of  
13 passengers. The objects found are consistent with the pre-formed fragments  
14 in the 9N314-model warhead carried on the 9M38-series of missiles as  
15 installed in the Buk, Buk-M1 of Buk-M1-2 ground to air missile system.  
16
- 17 8. *Blast* Simulation of the blast after detonation of the 9N314-model warhead  
18 creates an area of very high pressure (shock wave) near the cockpit. The  
19 simulation showed that the blast causes structural damage to the aeroplane  
20 structure up to 35 metres from the point of detonation. This was consistent  
21 with the damage found on the aeroplane wreckage.  
22
- 23 9. *Failure sequence* After the initial impact, the aeroplane broke up as follows:  
24 a. There was an almost simultaneous separation of the cockpit from the  
25 forward part of the fuselage when the high-energy objects penetrated  
26 the cockpit. The cockpit from the forward part of the fuselage came to  
27 rest 2.3 kilometres from the last position recorded on the Flight Data  
28 Recorder.  
29 b. The centre and rear part of the fuselage remained, initially, intact,  
30 gliding aerodynamically and came to rest about 8.5 kilometres to the  
31 east. The centre section travelled further than the rear part of the  
32 fuselage. This part came to rest upside down in two parts with the  
33 centre section beyond the empennage. The wreckage caught fire.  
34 c. Some seats fell free of the fuselage, whilst others remained attached  
35 to the floor.  
36 d. The time between the start of the break-up and the impact with the  
37 ground could not be accurately determined, but the centre and rear  
38 parts of the aeroplane were estimated to have taken about 1 – 1.5  
39 minutes to reach the ground. Other, lighter parts, will have taken  
40 longer.

1 10. *Launch area* The missile was fired from within an area of about 250 km<sup>2</sup>, that  
2 is approximately 15 km by 17 km. This area is located to the south of, and  
3 including, the village of Snizhne, Ukraine.

#### 4 **4.3 Excluding other causes**

5 The Dutch Safety Board has investigated and analysed a number of different  
6 possible causes of the accident. The Safety Board excludes the following matters  
7 as having had a role in the accident to flight MH17.

- 8
- 9 1. *Crew* The flight crew members were properly licensed and qualified to  
10 conduct the flight. There is no evidence that the crew handled the aeroplane  
11 inappropriately nor were they under the influence of alcohol, drugs or  
12 medicine.
- 13
- 14 2. *Airworthiness and flight plan* The aeroplane was in an airworthy  
15 condition on departure from Amsterdam Airport Schiphol and there were no  
16 known technical malfunctions that could affect the safety of the flight. An Air  
17 Traffic Control flight plan had been filed and the flight crew had been provided  
18 with an operational flight plan, NOTAMs, loading and weather information.
- 19
- 20 3. *Loading and cargo* The mass and centre of gravity of the aeroplane  
21 were within authorised limits. There was no cargo classified as dangerous  
22 goods on board the aeroplane, nor was any evidence found of explosion with  
23 dangerous goods inside the aeroplane.
- 24
- 25 4. *Airspace* On 17 July 2014, airspace restrictions were in place for the  
26 eastern part of Ukraine and parts of the bordering airspace in the Russian  
27 Federation from ground level up to FL320. There were no restrictions for flight  
28 MH17 to fly in Dnipropetrovs'k Flight Information Region planned flight levels  
29 FL330 and FL350.
- 30
- 31 5. *Climb* The flight crew's decision not to accept the air traffic controller's  
32 request to climb from FL330 to FL350 was determined to be a normal  
33 operational consideration. Flying at the lower flight level had no influence on  
34 the ability of the surface to air missile to engage the aeroplane.
- 35
- 36 6. *Weather* The weather on the planned flight route showed the presence of  
37 thunderstorms moving north from the Black Sea. On request by the flight crew,  
38 the air traffic controller authorised flight MH17 to circumnavigate this weather.  
39 Flight MH17 did not deviate from the width of airway L980 by more than  
40 approximately 1.5 NM. In the last recorded position at 13.20:03 (15.20:03

- 1 CET), flight MH17 was within the width of airway L980. The weather had no  
2 influence on the accident to MH17.  
3
- 4 7. *Pre-existing damage* There was no indication of a presence of pre-  
5 existing airframe damage, including fatigue or corrosion or inadequately  
6 performed repairs. There was no indication of engine failure.  
7
- 8 8. *No warnings* Analysis of the Cockpit Voice Recorder and Flight Data  
9 Recorder confirmed the normal functioning of the aeroplane's systems prior to  
10 the accident. No warnings, failures or discrepancies were found in the data for  
11 the accident flight. No aural alerts or warnings of aircraft system malfunctions  
12 were heard on the Cockpit Voice Recorder. The communication between the  
13 flight crew members gave no indication of any malfunction or emergency prior  
14 to the occurrence. The engine parameters were consistent with normal  
15 operation during the flight. The recorded aircraft data showed no malfunctions,  
16 warnings, failures or discrepancies for the duration of the flight.  
17
- 18 9. *Other weapons*
- 19 a. *Air to air gunfire* The high-energy object damage was not caused by air to  
20 air gunfire because the number, the size and type of high-energy objects  
21 impact damage is not consistent with gunfire impact damage and the  
22 trajectories of the high-energy objects that struck the aeroplane are not  
23 parallel but converge to a single location close to, and above, the  
24 aeroplane.
- 25 b. *Air to air missile* The high-energy object damage was not caused by an  
26 air to air missile because there was no military aircraft in the area of flight  
27 MH17 to launch such a missile. Air to air missile warheads do not have  
28 butterfly or bow-tie shaped fragments, and an infra-red guided missile  
29 would have caused damage to the aeroplane nearer the engines.
- 30 c. It is extremely improbable that the aeroplane was struck by more than one  
31 weapon system simultaneously.  
32
- 33 10. *Other scenarios* Other possible scenarios that could have led to the  
34 disintegration of the aeroplane were considered and analysed. These  
35 scenarios were an on-board fire or a fuel tank explosion, the detonation of an  
36 explosive device inside the aeroplane, lightning strike, and impact by a meteor  
37 or space debris re-entering the atmosphere. All of them were excluded based  
38 on the available evidence.